



NOTE:
CONSULT GLAZING SYSTEM
MANUFACTURER TO ENSURE THAT
INSTALLATION PROCEDURES EXCEED
THE MANUFACTURERS INSTALLATION
RECOMMENDATIONS FOR RESISTING
ALL HORIZONTAL DESIGN LOADS BY
A MINIMUM OF 25%.

EXPRESS
EXPRESS FASHION OPERATIONS, LLC
d/b/a STORE DESIGN & CONSTRUCTION
1 Express Drive Columbus, Ohio 43230
Telephone: 614.474.4001 Express.com

[illegible]

1753

OUTLET
FALL 2014
140301

PROJECT INFORMATION: **EXPRESS**
TANGER OUTLET CENTER - BRANSON
 300 TANGER BLVD.
 SPACE NO.: 535
 BRANSON, MO 65616

REVISIONS:	
REQUIRED BY:	DATE:
ELITE CONSTRUCTION GROUP LAKE JACKSON, TX PHONE: 979-285-0712 NOTE: THESE PRINTS HAVE BEEN REDUCED BY 50 PERCENT. SCALE WILL BE 30 PERCENT OF WHAT IS NOTED ON PLANS	

* INDICATES NO REVISION TO THIS SHEET

SHREMSHOCK

Shremshock Architects, Inc.

6130 S. Sunbury Rd. Westerville, OH 43081

t: 614 545 4550 | f: 614 545 4555 | shremshock.com

Gerald S. Shremshock, Architect
Timothy J. Shremshock, Architect

DATE ISSUED: 07/18/14
DESIGNED BY: JEB
DRAWN BY: JEB
CHECKED BY: AEM/KMM

STOREFRONT DETAILS

DRAWING NUMBER:
A08.3

NOT USED

NOT USED

STOREFRONT DETAIL

STOREFRONT DETAIL

NOT USED

STOREFRONT DETAIL @ ENTRY DOORS

1 1/2" = 1'-0"

DRAWING NUMBER:

A08.3